## REMEDIAL SITE ASSESSMENT DECISION - EPA REGION II

Site Name: Alsy Manufacturing EPA ID#: NYD981184237 State ID#: 130027

Alias Site Names:

DECISION:	_ 144 [64]	
1. Further Remo	edial Site Assessment under CERCLA	A (Superfund) is <u>not</u> required because:
site a (Site	does not qualify for further remedial ssessment under CERCLA Evaluation Accomplished - SEA)	1b. Site may qualify for further action, but is deferred to:
	ity:   Higher  X   Lower	
much chance for soil an solvent/degreasers. On Department. There are	nd overland surface water runoff to occursite facilities have been often cited for 152,729 people on groundwater drinking	contamination have been covered by blacktop parking lot, precluder. Groundwater has received discharges of heavy metals and violations of their SPDES permit and by the Nassau County Healing wells within four miles of the site. The area is a wellhead and about 100 workers are onsite. There are no schools or days